## FIRE SAFETY CERTIFICATE

It is certified that Building of Shiksha International Academy, Khata No 247, Assessment No.11/3, House List No. 01, Hosahalli, Gollarapalya, Magadi Main Road Bengaluru, Comprised of Ground floor, First floor, Second floor, Third floor have complied with the fire prevention and fire safety requirements in accordance with rule of State/UT Fire Service Rules. The building has been inspected by the officers concerned of Fire Service on 13/05/2022 in the presence of Chairman Mr. L Chandrasekhar, Shiksha International Academy, Khata No 247, Assessment No.11/3, House List No. 01, Hosahalli, Gollarapalya, Magadi Main Road Bengaluru, and it is found that the building premises is safe and secure to be occupied for school purpose with effect from 17/05/2023 for a period of 1 year.

This Certificate
Affiliation purpose.

This Certificate is sued in English language against the request of the school for CBSE

Date:

Your's faithfully

Dated: 18/05/2022

Chief Fire Officer

Bangalore West, Sheshadri Road, Highground Fire Station Premises.

Bangalore - 560 009.

To, Shiksha International Academy, Khata No 247, Assessment No. 11/3, House List No. 01, Hosaballi, Gollarapalya, Magadi Main Road Bengalusu,s